

## DL512299 Technical Bulletin

Please note:

Failure to remove the protective shipping cap currently supplied with DL512299 may result in an ABS warning light being triggered.

*The cap creates interference within the magnetic pick up coil setting a fault code.*



Protective cover installed.



Always remove the protective cover before installation.