

These units are interchangeable

Although the unit you purchased may not look exactly like the one removed from the vehicle, it will install and operate with no modifications necessary.

2002 - 2003 SATURN VUE

Is your Saturn experiencing the problem of the starter staying engaged, after the engine has started? The electrical accessories (radio, power windows, blower motor) intermittently having a loss of operation?

According to general motors, the ignition lock bolt spring binding could cause the problem.

The correction for this problem is to replace the ignition and start switch-housing assembly. General Motor's part number is #22692788.

Caution:

IT IS RECOMMENDED BECAUSE OF THE COMPLEXITY OF THIS REPAIR, THAT THIS WORK BE DONE BY A CERTIFIED GENERAL MOTORS DEALERSHIP or APPROPRIATE CERTIFIED MECHANIC. THIS JOB DOES REQUIRE REMOVAL AND DISARMAMENT OF THE SUPPLEMENTAL RESTRAINT SYSTEM. (SRS)