STOP

Technical Bulletin
Important – Please Read!!

TBA0088 Revision Date: 8/24/06

The replacement alternator in the box may look different than the original... but the unit that you have purchased meets or exceeds the Manufacturer's specifications for correct vehicle performance.

Mitsubishi Version I

Mitsubishi Version II

Technical Support Hotline: 800-228-9672
M-F 5:30AM-5:00PM PST, Sat 6:00AM-2:30PM PST

STOP

Avertissement!
Advertencia!

TBA0088 Revision Date: 8/24/06

L'alternateur de rechange que vous trouverez dans la boîte peut paraître différent de l'original mais la pièce que vous avez achetée répond aux spécifications du fabricant, ou les dépasse, pour un fonctionnement correct du véhicule.

El alternador de repuesto en la caja puede verse diferente al original... pero la unidad que compro cumple o supera las especificaciones del fabricante para el funcionamiento correcto del vehículo.

Version Mitsubishi I
Versión Mitsubishi I

Mitsubishi II
Versión Mitsubishi II

Technical Support Hotline: 800-228-9672
M-F 5:30AM-5:00PM PST, Sat 6:00AM-2:30PM PST