

Part # C1134

Primary Cannot Read Secondary 9.5k - 17.0k Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking

