

Part # C1151

Primary Cannot Read Secondary 20.5k - 31.0k Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking

