



Technical Bulletin  
Important – Please Read!!

**TBH0014** Revised: 5/8/2015

The replacement wheel hub in the box may look different than the original... but the unit that you have Purchased meets or exceeds the Manufacturer's Specifications for correct vehicle performance.



Version I



Version II



Technical Support Hotline: 800-228-9672  
M-F 5:30AM-5:00PM, S-S 6:00AM-2:30PM PST



Boletín Técnico  
Importante: Favor de Leer

**TBH0014** Revised: 5/8/2015

El balero masa de repuesto en la caja puede verse diferente al original... pero la unidad que compro cumple o supera las especificaciones del fabricante para el funcionamiento correcto del vehículo.



Version I



Version II



Línea Asistencia Técnica: 800-228-9672  
L-V 5:30AM-5:00PM, S-D 6:00AM-2:30PM PST