

83-83 6.9 L Diesel originally was equipped with a Delco Remy Direct Drive 19988423 starter *Fig.1*

Due to fly wheel engagement issues with the Delco Remy starter Ford Service (described in Ford document TSB 85-10) converted some vehicles with problems to a Mitsubishi starter M3T90072 *Fig.2* and also included a mandatory flywheel change (E3TZ6384-A) The M3T90072 model starter is an Offset Gear Reduction model that provided increased performance over the Direct Drive model.

Mitsubishi discontinued manufacturing the M3T90072 model and now services it with a M8T50171 *Fig.3* Planetary Gear Reduction model that will interchange with the M3T90072 version despite appearance differences.

Additional Option:

The Nippondenso model *Fig.4* might have been used as a replacement alternative to the above mentioned Mitsubishi models.



*Fig.1* 1998423



*Fig.2* M3T90072



*Fig.3* M8T50171



*Fig.4* 028000-5882