

Gabriel® Answerman Tip

Gabriel Technical Bulletin

THE ANSWERMAN
800.999.3903 | gabriel.com



G56514 Ultra Strut – Front Right

97-01 Lexus ES300; 97-04 Toyota Avalon; 97-01 Toyota Camry; 99-03 Toyota Solara

Installation Difficulty is High

The upper strut rod shoulder has two flats that must align with corresponding flats formed in the mating surfaces of the strut mount. These parts must be interlocked by the flats so that the rod will not turn relative to the mount when tightening to achieve final torque. Failure to maintain this alignment may result in:

- Loosening of the fastened joint
- Development of noise due to a loose joint
- Eventual failure of the strut mount and/or strut



Representative - For illustrative purposes only

Suggested Alternative:

ReadyMount # G56931 is recommended as an alternative to Ultra Strut # G56514 to avoid servicing difficulties and assembly errors.

The Original
Gabriel®

Ride the independent spirit™

April 2013. PN G56514