

WARNING

**CHRYSLER, DODGE 2.7L
VIN R, U, V (1998-2007)**

Sludge buildup in the oil passages is a common problem in these engines.

When replacing the timing components pay close attention to the oil passages feeding the timing chain tensioner(s). Restricted oil passages will cause inadequate timing chain tension and could result in engine damage.

As a preventive maintenance, we recommend one of the following engine flush products with EVERY oil change:

- Gunk Motor Flush #MF3
- STP Motor Treatment #17173
- Seafoam Motor Treatment #SF16