

# **WARNING**

**GM 2.0L, 2.2L, 2.4L  
VIN P, F, D, B (2002-08)**

*Sludge buildup in the oil passages is a common problem in these engines.*

**When replacing the timing components pay close attention to the oil passages feeding the timing chain tensioner(s).**

**Restricted oil passages will cause inadequate timing chain tension and could result in engine damage.**

**As a preventive maintenance, we recommend one of the following engine flush products with EVERY oil change:**

- Gunk Motor Flush #MF3
- STP Motor Treatment #17173
- Seafoam Motor Treatment #SF16