



Technical Bulletin
Important – Please Read!!

TBH0013 Revised: 3/24/2015

The replacement wheel hub in the box may look different than the original... but the unit that you have Purchased meets or exceeds the Manufacturer's Specifications for correct vehicle performance.



Early Style

Late Style



Technical Support Hotline: 800-228-9672
M-F 5:30AM-5:00PM, S-S 6:00AM-2:30PM PST



Boletín Técnico
Importante: Favor de Leer

TBH0013 Revised: 3/24/2015

El balero masa de repuesto en la caja puede verse diferente al original... pero la unidad que compro cumple o supera las especificaciones del fabricante para el funcionamiento correcto del vehículo.



Estilo previo de
carrosería

Estilo posterior de
carrosería



Línea Asistencia Técnica: 800-228-9672
L-V 5:30AM-5:00PM, S-D 6:00AM-2:30PM PST