

## Part # C1222

### Primary Cannot Read Secondary 8.5k - 14.5k Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking

