

Part # C835

Primary .2 - .8

Secondary 5.0k - 11.0k

Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking
3. Check for oil leakage
4. Bracket will appear to be loose

