

Part # C847

Primary .3 - .8

Secondary 4.5k - 9.5k

Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking
3. Check for oil leakage
4. Bracket will appear to be loose

