



Technical Bulletin  
Important – Please Read!!

**TBA0106** Revision Date: 1/28/08

The replacement alternator in the box may look different than the original... but the unit that you have purchased meets or exceeds the Manufacturer's specifications for correct vehicle performance.

**Bosch Version**



**Valeo Version**



**Hitachi Version**



Technical Support Hotline: 800-228-9672  
M-F 5:30AM-5:00PM PST, Sat 6:00AM-2:30PM PST



Avertissement!  
Advertencia!

**TBA0106** Revision Date: 1/28/08

L'alternateur de rechange que vous trouverez dans la boîte peut paraître différent de l'original mais la pièce que vous avez achetée répond aux spécifications du fabricant, ou les dépasse, pour un fonctionnement correct du véhicule.

El alternador de repuesto en la caja puede verse diferente al original... pero la unidad que compro cumple o supera las especificaciones del fabricante para el funcionamiento correcto del vehículo.



**Version Bosch**  
**Versión Bosch**



**Version Valeo**  
**Versión Valeo**



**Version Hitachi**  
**Versión Hitachi**



Technical Support Hotline: 800-228-9672  
M-F 5:30AM-5:00PM PST, Sat 6:00AM-2:30PM PST