GM & SATURN 2.0L, 2.2L, 2.4L

Timing Chain Guide and Arm Installation

BOLT TORQUE SPECIFICATIONS

Fixed Left Hand Chain Guide tighten bolts to 10 Nm, 89 inch lbs.

Fixed Upper Chain Guide tighten bolts to 10 Nm, 89 inch lbs.

Chain Tensioner Pivot Arm tighten bolts to 10 Nm, 89 inch lbs.

Not matching the OEM torque specifications can possibly lead to the part failing and severe engine damage.