


Part # C1000

Primary .2 - .8

Secondary 9.0k - 17.0k

Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking



Primary Check
.2 - .8

Secondary Check
9.0k - 17.0k