

Part # C1028




Primary .9 - 1.6

Secondary 23.0k - 33.5k

Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking

Primary Check
.9 - 1.6



Secondary Check
23.0k - 33.5k

