

Part # C1124


Primary .2 - .8

Secondary 4.5k - 11.5k

Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking

Primary Check
.2 - .8



Secondary Check
4.5k - 11.5k

