


Part # C1176

Primary .8 - 1.5

Secondary 10.5k - 17.5k

Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking



**Primary Check
.8 - 1.5**

**Secondary Check
10.5k - 17.5k**