

Part # C837

Primary 1.2 - 1.9

Secondary 7.0k - 13.0k

Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking
3. Check for oil leakage

