

Part # C838G

Primary 1.2 - 1.9

Secondary 9.0k - 15.0k

Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking
3. Check for oil leakage

