

# Part # C861

**Primary 1.0 - 1.8**

**Secondary 8.5k - 14.0k**

## Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking

