

# Part # C872

Primary .4 - 1.2

Secondary 12.5k - 18.5k

## Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking

