

# Part # C879

**Primary .7 - 1.4**

**Secondary 8.0k - 14.0k**

## Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking

