

# Part # C914


**Primary .2 - .7**

**Secondary 8.5k - 13.0k**

## Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking

**Primary Check  
.2 - .7**



**Secondary Check  
8.5k - 13.0k**

