

Part # C924



Primary .3 - .9

Secondary 11.5k - 17.5k

Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking

Primary Check
.3 - .9



Secondary Check
11.5k - 17.5k