

Part # C926


Primary .2 - .7

Secondary 8.5k - 13.5k

Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking

Primary Check
.2 - .7



Secondary Check
8.5k - 13.5k

