

Part # C928

Primary 1.2 - 1.8

Secondary 8.0k - 13.0k

Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking

