


Part # C932

Primary .7 - 1.4

Secondary 10.0k - 15.5k

Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking



Primary Check
.7 - 1.4

Secondary Check
10.0k - 15.5k