


Part # C938

Primary .3 - 1.0 Secondary 10.5k - 16.5k Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking

Primary Check
.3 - 1.0



Secondary Check
10.5k - 16.5k

