

# Part # C941

Primary .2 - .8

Secondary 22.5k - 31.0k

## Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking

