

Part # C969

Primary .3 - .9

Secondary 9.5k - 14.5k

Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking

