

# Part # C971

**Primary .2 - .9**

**Secondary 9.5k - 14.5k**

## Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking

