


Part # C991

Primary .3 - .9


Secondary 18.0k - 23.5k

Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking



Primary Check
.3 - .9



Secondary Check
18.0k - 23.5k