

# Part # C999

Primary .2 - .7

Secondary 12.5k - 18.0k

## Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking

